

6.4.2 When monitoring for a category A stressor levels outside of the boundary area the required recordkeeping requirements are identical to those listed in 6.4.1 with the following exceptions:

- a. No personal protective equipment is required since the sampling is outside of the boundary.
- b. If the stressor concentration is over the limit, corrective action must be documented.

6.4.3 When monitoring for category B and C stressors recordkeeping requirements are identical to those in 6.4.1 and 6.4.2b, although boundary numbers will not always be required as determined by the OSH office.

6.4.4 Category A stressor operations shall be monitored or visually inspected by Code 106.1 or 106.3 for post work disestablishment of boundary. The following records are required:

- a. I - Boundary number.
- b. I - Stressor name.
- c. Review of post-work environmental samples (if any) and work area certification for compliance to the standard for the stressor concerned.
- d. I - Date of control area disestablishment.
- e. Time controlled area disestablishment.

NOTE: These work process category records may be separate or combined as needed, but the minimum data elements must be available.

6.5 Training

6.5.1 All Shipyard personnel shall receive proper training in accordance with reference (a) for those operations which could or do generate stressor exposure levels in excess of their PEL or AL.

- a. Formal training with a training plan shall be required for category A stressors. Formal training is at least one hour.
- b. As with A stressors, category B and C stressors may require formal training or a formal briefing. The determination of the need for training or briefing will be made by the OSH office and identified in procedural control instructions.